

C. MULHOLLAND
RT. 4 BOX 424 H
NO WILKESBORD, NC
28659



John Hancock

Patriot



U.S. Postage 10¢

Robert Fabris
3626 Morrie Dr.
San Jose, Ca 95127

Bob;

Ron's resequencing program will not work on my machine and I think it may be in the object code on various machines. I get two ← followed by 258 ↓ then another 258 → , 258 × , 258 ÷ OCT

Had lunch with Jerry Tindle in Texas monday and we compared notes on the keyboards. We each feel the users would be better off waiting for your interface. I so state in a letter I'm enclosing with each schematic I send. Jerry and I are working up a light pen input and will keep you posted.

His machine will not run Ron's program and he gets the same results I get. Could we get Ron's address or get him to give us some ideas thru the Arcadian?

Thanks much,
Ed Mulholland

Ron Schweitzer
1112 Halley Ave
Rapid City SD

57701

342-6202
605